

**IMPORTANT  
PRECAUTIONARY SAFETY ALERT**

**Voluntary Recall Date:** February 22, 2021

**Name of product:** Clip Clop Activity Rattle / Clopette Activity Rattle

**Manufacturer:** Playgro



**Potential Hazard:** The beads may become dislodged from the circular bar over time, as a secondary layer of protective reinforcement may not be present in some items, potentially impacting durability.

**Risk Level:** Product meets global safety standards. Product may not adhere to manufacturer's supplemental safety standards.

**Description:** This voluntary recall involves Clip Clop Activity Rattle and Clopette Activity Rattle, sold in blue and pink. The affected model numbers are 0101145 (blue) – **Batch # 009986** and 0183303 (pink) – **Batch # 009837**. The voluntary recall only includes items which are made in China. Those made in Bangladesh are NOT impacted.

Locate the Batch # of your item on the label here



**Sold At:** Toys“R”Us from September 2020 through February 2021.

**Further Action:** If you have purchased one of the affected rattles, you are asked to stop using it and return it to the retailer from which it was purchased for a replacement at your convenience.

If you have any queries please do not hesitate to contact Toys“R”Us on:

**Malaysia**                      **03 5634 3930**      [help@toysrus.com.my](mailto:help@toysrus.com.my)

**Singapore**                     **6733 0190**        [help@toysrus.com.sg](mailto:help@toysrus.com.sg)

We apologize for any inconvenience and sincerely thank you for your co-operation.

Thank you,

Toys“R”Us (Asia) Limited